




# Replaces Toro Reelmaster 5300-D Parts

Verti-Cut Unit

Left-Hand Groomer Kit - Model 03810



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Toro Reelmaster 5300-D Parts

Verti-Cut Unit

Left-Hand Groomer Kit - Model 03810



| Item No | R&R Part No.      | OEM Part No.                                                                                                                            | Description                          | Qty Req | Order Quantity |
|---------|-------------------|-----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|---------|----------------|
| 70      | <b>R93-9783</b>   | 93-9783                                                                                                                                 | O-Ring - Reel                        | 1       |                |
| 71      | <b>R253-83</b>    | 253-83                                                                                                                                  | Seal - Oil 7/8 OD x 5/8 ID           | 1       |                |
| 72      | <b>R95-9619</b>   | 95-9619                                                                                                                                 | Key - Square 1/8 x 1/8 x 5/16        | 1       |                |
| 73      | <b>R458461</b>    | 32151-34                                                                                                                                | Snap Ring                            | 1       |                |
| 74      | <b>R3234-14</b>   | 3234-14,<br>3234-23                                                                                                                     | Bolt - Hex Serrated Washer HD        | 3       |                |
| 75      | <b>R3234-24</b>   | 3234-24,<br>3234-8,<br>3234.24,<br>66-9301                                                                                              | Bolt - Hex Ser Was HD 3/8-16 x 1-1/4 | 2       |                |
| 75      | <b>R33105-030</b> | 33105-030                                                                                                                               | Bolt - Hex Washer M10                | 2       |                |
| 76      | <b>R38-7820</b>   | 100-1048,<br>251-277,<br>251-5,<br>38-7820                                                                                              | Bearing - Ball                       | 1       |                |
| 76      | <b>R343667</b>    | 109966,<br>251-6,<br>38-7820                                                                                                            | Bearing - Ball                       | 1       |                |
| 77      | <b>R88-7200</b>   | 88-7200                                                                                                                                 | Washer - Flat                        | 1       |                |
| 78      | <b>R3253-4</b>    | 01-166-0110,<br>01-166-0510,<br>23-10-GD,<br>24-7170,<br>30-8520,<br>3253-4,<br>48-9350,<br>48-9360,<br>48-9570,<br>68-9420,<br>99-7577 | Washer - Lock 5/16 Zinc              | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Toro Reelmaster 5300-D Parts

Verti-Cut Unit

Left-Hand Groomer Kit - Model 03810



| Item No | R&R Part No.     | OEM Part No.                                                                                        | Description                      | Qty Req | Order Quantity |
|---------|------------------|-----------------------------------------------------------------------------------------------------|----------------------------------|---------|----------------|
| 79      | <b>R322-3</b>    | 01-150-1420,<br>01-178-0506,<br>20-24-AD,<br>20-24-AGD,<br>322-3,<br>48-9270,<br>513339,<br>908017P | Bolt - Hex HD 5/16-18 x 3/4      | 1       |                |
| 79      | <b>R400184</b>   | 322-2,<br>322-3                                                                                     | Screw - 5/16-18 x 3/4 Hex        | 1       |                |
| 80      | <b>RA170040</b>  | 32120-42,<br>52-6640,<br>74-9900,<br>SG427625                                                       | Ring - Snap                      | 1       |                |
| 81      | <b>R445795</b>   | 30-4020,<br>32128-25                                                                                | Nut - 5/16-18 Flanged            | 2       |                |
| 82      | <b>R104-8300</b> | 104-8300,<br>104-8300 ,<br>119-4041                                                                 | Locknut - 5/16-18 Flanged Y/Zinc | 2       |                |
| 83      | <b>R95-0707</b>  | 95-0707                                                                                             | Bearing - Self Aligning          | 2       |                |
| 84      | <b>R110-7352</b> | 110-7352                                                                                            | Screw - HOC 2 5/8 Stainless      | 2       |                |
| 85      | <b>R3296-48</b>  | 119-4039,<br>32146-7,<br>3296-34,<br>3296-48                                                        | Locknut - 7/16-14 ESNA           | 2       |                |
| 86      | <b>R700414</b>   | 302-11,<br>302-19,<br>302-4,<br>32-8170                                                             | Zerk - Grease 1/4-28 45 Deg      | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Reelmaster 5300-D Parts

Verti-Cut Unit

Left-Hand Groomer Kit - Model 03810



| Item No | R&R Part No. | OEM Part No.                                                                                                                                   | Description                            | Qty Req | Order Quantity |
|---------|--------------|------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|---------|----------------|
| 86      | R302-5       | 21-6010,<br>302-11,<br>302-37,<br>302-47,<br>302-5,<br>302-57,<br>302-58,<br>302-6,<br>31-0300,<br>32-9660,<br>60-0800,<br>62-3880,<br>92-4181 | Fitting - Grease                       | 1       |                |
| 87      | R237-22      | 107-8844,<br>237-22,<br>237-78                                                                                                                 | O-Ring                                 | 1       |                |
| 88      | R32127-46    | 32127-46,<br>3296-60                                                                                                                           | Locknut                                | 2       |                |
| 89      | R32151-60    | 32151-60                                                                                                                                       | Ring - Snap                            | 1       |                |
| 90      | R32128-21    | 32128-21                                                                                                                                       | Locknut - Flanged 3/8-16 Whiz Top Lock | 1       |                |
| 91      | R101526      | 01-150-0970,<br>01-178-0620,<br>20-53-AGD,<br>321-11,<br>3224-8,<br>323-11,<br>323-12,<br>323-31,<br>323-4,<br>323-47                          | Bolt - Hex HD 3/8-16 x 2-1/2 GR5       | 4       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Reelmaster 5300-D Parts

Verti-Cut Unit

Left-Hand Groomer Kit - Model 03810



| Item No | R&R Part No. | OEM Part No.                                                                                                                                                                                                                                                                                                                   | Description                  | Qty Req | Order Quantity |
|---------|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|---------|----------------|
| 92      | R453011      | 01-166-0100,<br>01-166-0120,<br>01-166-0270,<br>01-166-0500,<br>01-166-0600,<br>01-166-0620,<br>132-4593,<br>2356-3,<br>237-12,<br>24-10-AD,<br>24-11-AD,<br>24-11-BD,<br>24-12-AD,<br>24-12-BD,<br>30-9310,<br>32-8190,<br>3256-24,<br>3256-3,<br>3256-36,<br>3256-4,<br>453011,<br>47-9950,<br>48-9220,<br>513458,<br>7-0052 | Washer - Flat 3/8 SAE Y/Zinc | 8       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.