



NGK Spark Plug - R7376-10

RN4457



Replaces

Autolite	AR5383
Denso	IW01-31, IW06-31

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Gritmaster

309 Percy Osborn Road Morningside, 4001
0313035785

<https://gritmaster.rrproducts.com/>