



NGK Spark Plug - BR2-LM

RN5798



Replaces

Autolite	458
Bosch	WR11E0
Briggs & Stratton	29683, 298809, 391919, 392588, 394539, 394812, 491167, 492167S, 493944, 499730, 5062 A&B&C, 555132, 591040, 591868, 696798, 697858, 796112, 799876, 802592
Champion	5861, 861, 861-1, 861S, 868, 868-1, 868S, 973, J19LM, J19LMC, J2YLE, J2YXLE, RJ19HX, RJ19LM, RJ19LMC, RJ2YLE, RJ2YXLE
Denso	W9LM-US, W9LMR-US
MotorCraft	A11LM
R&R Products	RN1147, RN1731

Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

Gritmaster

309 Percy Osborn Road Morningside, 4001
0313035785

<https://gritmaster.rrproducts.com/>