



NGK Spark Plug - ZFR5FGP

RN7098



Replaces

Autolite	AP985
Bosch	FR8HPP30X, FR8LPP302X, FR8LPP30X
Champion	3318, 3318-2

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Gritmaster

309 Percy Osborn Road Morningside, 4001
0313035785

<https://gritmaster.rrproducts.com/>