


Replaces Toro Greensmaster 3050 Parts



4-Bolt Cutting Unit - Models 04405, 04406, 04408 & 04409 Minuteman Roller System





Replaces Toro Greensmaster 3050 Parts



4-Bolt Cutting Unit - Models 04405, 04406, 04408 & 04409 Minuteman Roller System

1 1	RMT8001	an Roller Systems	Minuteman Front Grooved Roller System			
	Tech Note: Con	anlata rollar systems i	Minuteman Front Grooved Roller System			
		anlata rollar systems i		0		
Minute	eman Rollers (ipiete roller systems i	nclude roller and two brackets with bearings.:			
		Only				
2 I	RM513		Minuteman Grooved Roller Only	0		
7	Tech Note: Use with Minuteman Roller Bracket System Only:					
Other	Parts Availab	le				
3 I	RT821		Bracket Assy - Front LH/RH	0		
	Tech Note: Incl Screw:	udes RT8210 Bearing	& Locking Collar, RMM606 Washer, R3219-5 Nut & R	RMM607		
4 I	RMMB157		Bearing w/Locking Collar	0		
5 I	RT8210		Block - Height Adj	0		
6 I	RMM606		Washer - Lock 3/8 Zinc Internal Tooth	0		
7 I	R3219-5	01-188-0820, 22-15-BJD, 22-15-BJKD, 3219-5	Nut - 1/2-20	0		
8 I	RMM607	01-158-0610, 01-191-0820, 21-3900, 3220-5, 45-0170, 5/1/3220	Nut - Jam 1/2-20 Zinc	0		
9 I	RMM608		Screw - 8-32 x 5/16 SS Socket Head	0		
10 I	RMM3		End Hub - 7/8 ID	0		
11 I	RT821P		Plate - For RT821 Bracket	0		

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster 3050 Parts



4-Bolt Cutting Unit - Models 04405, 04406, 04408 & 04409 Minuteman Roller System

Item R&R	OEM	Description	Qty	Order
No Part No.	Part No.		Req	Quantity
12 RT821B		Ball - For RT821 Bracket	0	