




Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 75955
52in Side Discharge Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 75955
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
---------	--------------	--------------	-------------	---------	----------------

Belts

20	R115-7426	115-7426	Belt- V	1	
----	------------------	----------	---------	---	--

Rotary Blades

30	R105-7781-03	105-7781-03, 140-1242	Mower Blade - 18 in High-Flow	3	
30	R108-1117	108-1117	Mower Blade Kit - 18 in High-Flow Set/6	1	
30	R105-7779-03	105-7779-03	Mower Blade - 18 in Recycler	3	
30	R110-0408	110-0408	Mower Blade Kit - 18 in Recycler Set/6	1	

Wheels

40	R68-2730	1-603299, 68-2730	Wheel - Anti Scalp	3	
----	-----------------	----------------------	--------------------	---	--

Other Parts Available

70	R106-3253-01	106-3253-01, 108-7766-03	Plate-Hinge, Front	1	
----	---------------------	-----------------------------	--------------------	---	--

Tech Note: (2012-2019)-312000001-404971756:

71	R104-8301	104-8301, 104-9301, 109-6658, 133-7570	Locknut - 3/8-16 Nylon Flanged	44	
----	------------------	---	--------------------------------	----	--

Tech Note: (2011-2019)-311000001-404971756:

72	R108-4059-01	108-4059-01, 108-7767-03	Plate-Hinge, Rear	1	
----	---------------------	-----------------------------	-------------------	---	--

Tech Note: (2013-2019)-313000001-404971756:

73	R106-3246-01	106-3246-01	Deflector	1	
----	---------------------	-------------	-----------	---	--

Tech Note: (2012-2019)-312000001-404971756:

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 75955
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
74	R151416	108-5029, 110-0759, 151416	Deflector - Long	1	
75	R106-3248-03	106-3248-03	Strap - Discharge	1	
76	R3231-4	01-157-0440, 01-173-0612, 3231-4	Bolt - Carriage 3/8-16 x 1-1/2	4	
<i>Tech Note: (2012-2019)-312000001-404971756:</i>					
77	R108-2792	108-2792	Rubber Deflector Assy	1	
<i>Tech Note: (2012-2019)-312000001-404971756:</i>					
78	R3296-47	3296-47	Locknut - 5/16-18 Jam Nyloc	1	
79	R108-4052	108-4052	Spring - Torsion	1	
80	R322-50	322-50	Bolt - Hx HD 5/16-18 x 7 1/2	1	
81	R98-5967	98-5967	Spacer-Wheel	1	
82	R108-5388	108-5388	Bolt - Hx HD 3/8-16 x 7 1/2	1	
83	R115-7455-01	115-7455-01	Baffle Assy	1	
84	R3231-27	3231-1, 3231-27	Bolt - Carriage 3/8-16 x 7/8	1	
85	R98-7913	98-7913	Spacer - Tube	1	
86	R98-7912	98-7912	Bushing - Spanner Wheel	1	
87	R323-23	01-150-0810, 01-178-0636, 20-60-AGD, 323-23	Bolt - Hex HD 3/8-16 x 4-1/2	1	
88	R51-4060	51-4060	Bolt - Blade	3	
<i>Tech Note: (2010-2019)-310000001-404971756:</i>					

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 75955
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
89	R103-0865	103-0865	Washer - Blade Bolt HD	3	
96	R92-5836	92-5836	Flat Washer - Hardened	3	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>					
97	R3296-67	3296-67	Locknut - 3/4-16 Heavy Jam RH Thread	3	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>					
100	R115-7450	115-7450	Pulley - 6.75 in Dia with 1.75 Bore	3	
101	R114-8195	114-8195, R & R ONLY	Bolt- Ribbed Neck	18	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>					
102	R32128-43	30-8990, 32128-43, 3290-357	Nut - Flanged Whiz - 3/8-16	3	
103	R112-4212	112-4212	Mount-Pulley	1	
104	R323-11	01-150-1440, 01-178-0618, 20-52-AD, 3224-7, 323-11	Bolt - 3/8-16 x 2 1/4 GR5	2	
105	R104-0151	104-0151	Spacer	1	
106	R116-6317	116-0133, 116-6317	Spring - Extension	1	
<i>Tech Note: (2013-2019)-313000001-404971756:</i>					
107	R114-5867	114-5867	Anchor - Spring - Tall	1	
116	R107-8541-01	107-8541-01	Baffle - Discharge	1	
120	R109-7952	109-7952	Deck Strut Assy	2	
121	R109-5013	109-5013	Panhard Rod Assy	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 75955
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
122	R32128-37	32128-37	Nut - 7-16-14 Hx Serr Fl	2	
123	R325-17	01-150-0640, 01-150-0850, 01-178-0832, 01-178-0836, 20-97-AGD, 325-17, 325-18, 48-9260	Bolt - Hex Head	1	
124	R109-5009	109-5009	Bushing - Suspension - Rubber	6	
125	R116-0797-03	116-0797-03	Link-Lift - Deck	1	
126	R116-0780	116-0780	Bolt - Hx HD Fl Shoulder	2	
127	R453022	01-166-0480, 01-166-1220, 21-3880, 217-21, 30-8550, 30-9110, 3256-28, 3256-44, 46-9030, Mar-71	Washer - 3/4 SAE	2	
128	R32128-23	32128-23, 3218-23, 99-5107	Nut - Lock Hex Flanged 1/2-13	6	
129	R109-5010	109-5010	Spacer	6	
131	R3233-34	3233-34	Carriage Bolt - 1/2-13 x 2 1/2 Grade 5	3	
132	R127-0560	127-0560	Spindle Assy - No Grease	3	
133	R127-0557	127-0557	Spindle Hub Assy w/Studs	3	
134	R116-0720	116-0720	Bearing - Ball - Special Triple Seal	6	
135	R127-0554	127-0554	Spacer - Bearing	3	
136	R127-0556	127-0556	Shaft- Spindle	3	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

*Zero Turn Mower with 52in deck - Model 75955
52in Side Discharge Deck*



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
140	R116-0886	116-0886	Spring - Extension	1	
141	R121-7975-01	121-7975-01	Plate - Skid	1	
142	R115-7461-01	115-7461-01	Baffle Assy	1	
143	R116-0459-03	116-0459-03	Lift - Rear Deck	1	
144	R126-2475-03	116-2217-03, 126-2475-03	Decklift - Front	1	
145	R114-5870	114-5870	Idler Arm Assy with Bushings	1	
146	R1-303514	1-303514	Bearing - Flanged	2	
147	R132-4724	132-4724	Pin - Spring Anchor	1	
148	R109-9066	109-9066	Yoke - Adjust - Deck	4	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.