

## 3/4 PVC Union Split Nut Kit



RGSNK007



## **Details**

Split Nut Repair Kit is designed to replace broken union nuts on all True Union 2000 Ball Valves and Sch 80 Union 2000 fittings. Kit includes: 2-Split Nut Halves 1-SS316 Gear Clamp. Full valve pressure rating maintained.

**Specifications** 

Manufacturer Spears

**Gritmaster** 

309 Percy Osborn Road Morningside, 4001

https://gritmaster.rrproducts.com/